


Art.: 3865

Manguito Anti Electrólisis M-H / Anti Electrolysis Fitting M-F

Características	Features
<p>Estos manguitos garantizan la eliminación de pares galvánicos producidos en una conducción mixta en la que existan elementos de diferente naturaleza y composición.</p> <p>Adaptados para cualquier tipo de instalación hidráulica, calefacción o neumática.</p> <p>Ideal para agua caliente o fría, aceites varios y aire comprimido.</p> <ol style="list-style-type: none"> Núcleo de poliamida 6.0 (nylon). Camisa exterior de cobre (Cu) 99,9%. Temperaturas mínima y máxima de trabajo: -20° C a 90° C (air). 0° C to 80° C (agua). Inflamabilidad: Auto extingible. Rosca interior (hembra) y exterior (macho) gas (BSP) según ISO 228/1. Presión máxima de trabajo 10 bar (PN10). 	<p>These fittings guarantee the elimination of produced galvanic pairs in a mixed conduction in which elements of different nature and composition.</p> <p>Adapted for any kind of hydraulic, pneumatic or heating installation.</p> <p>Ideal for cold and hot water, oils and compressed air.</p> <ol style="list-style-type: none"> Core made of polyamide 6.0 (nylon). Outer copper coating (Cu) 99,9%. Minimum and maximum working temperature: -20° C to 90° C (air). 0° C to 80° C (water). Flammability: Self-extinguishing. Inner (female) and outer (male) threads gas (BSP) according to ISO 228/1. Maximum working pressure 10 bar (PN10).



Nº	Denominación / Name	Material / Material
1	Cuerpo / Body	Nylon PA6 / Nylon PA6
2	Funda / Cover	Cobre (99,9%) / Copper (99,9%)

Ref.	Dimensiones / Dimensions (mm.)					Peso / Weight (Kg)
	R	P	H	D	t	
3865 04	1/2"	15	41	28	14	0,025
3865 05	3/4"	19	42	35	15	0,040

Consideraciones

- El apriete excesivo de la pieza metálica sobre el manguito provoca una situación de sobrecarga.
- El deterioro de la poliamida se ve acelerado por la combinación de agresiones mecánicas (esfuerzos de carga, vibraciones, etc.) y térmicas (altas temperaturas).

Features

- Over tightening the metal connector on the fitting causes an overload situation.
- Polyamide deterioration is accelerated by the combination of mechanical action (load efforts, vibration, etc.) and thermal (high temperature).